

**Figure Three** shows the Ordnance survey map from 1888-1913 compared to that of today. The course of the river has altered significantly and many of the historic field boundaries are no longer present. This map illustrates the opportunity to restore the Afon Tywi to a more natural course, providing benefits to the SAC condition and for water management in the floodplain.

